SOP: Transportation of liquid helium vessel.

Only trained persons should transport vessels containing liquid helium.

- 1. Use shoes which are covered properly by the trousers, or use shoeswhich easily may be removed. Use eye protection and gloves.
- 2. Push the container carefully through the corridors in order to avoid damage to the container.
- 3. If you have to use a lift between floors, put the container in the lift and walk up (down) the stairs. Be sure that nobody else uses the lift and put a poster with "Liquid nitrogen/helium. No entrance" on the container.